EAST Search History

EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L11	1	"5650241".pn.	US-PGPUB; USPAT	OR	ON	2010/05/18 10:50
L12	136	(429/27-29.ccls. h01m012\$. ipc. or h01m12\$.ipcr.) and button and ((first with second) or two) near4 (cathode or oxygen or air)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR ON		2010/05/18 11:04
L13	115	L12 and (@ad<"20030905" @rlad<"20030905" @ptad<"20030905")	US-PGPUB; USPAT; EPO; JPO; DERWENT			2010/05/18 11:04
L14	15	(dual adj (cathode or electrode)) same (metal adj air or zinc adj air)	US-PGPUB; USPAT; EPO; JPO; DERWENT	O;		2010/05/18 11:05
L15	322	((dual or double or two or second) with (cathode or electrode or positive)) same (metal adj air or zinc adj air) adj (battery or cell)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR ON		2010/05/18 11:05
L16	270	15 and (@ad<"20030905" @rlad<"20030905" @ptad<"20030905")	US-PGPUB; USPAT; EPO; JPO; DERWENT			2010/05/18 11:06
L17	230	16 not 13	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR ON		2010/05/18 11:06
L18	71	17 and insulat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR ON		2010/05/18 11:06
L19	351	((dual or double or two or second) with (cathode or electrode or positive)) and (metal adj air or zinc adj air) adj (battery or cell).ti,ab.	US-PGPUB; USPAT; EPO; JPO; DERWENT	USPAT; EPO;		2010/05/18 11:10
L20	299	19 and (@ad<"20030905" @rlad<"20030905" @ptad<"20030905")	US-PGPUB; USPAT; EPO; JPO; DERWENT	PO;		2010/05/18 11:10
L21	94	20 and insulat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2010/05/18 11:10
L22	63	21 not 18	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2010/05/18 11:10

L23		electrode and (metal adj air	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2010/05/18 11:12
L25	169	@rlad< "20030905"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2010/05/18 11:12
L26	89	25 and insulat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2010/05/18 11:12
L27	56	26 not 21 not 18	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2010/05/18 11:13

EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	42	((metal adj air or zinc adj air) near (cell or battery) and cathode with (two or second) and contact).clm.	US-PGPUB; USPAT; UPAD	OR	ON	2010/05/18 10:40
<u> </u>	23	((metal adj air or zinc adj air) near (cell or battery) and cathode near3 (two or second) and contact).clm.	US-PGPUB; USPAT; UPAD	OR	ON	2010/05/18 10:41
L3	0	((metal adj air or zinc adj air) near (cell or battery) and cathode near3 (two or second) and negative with (lid or cas\$3)).clm.	US-PGPUB; USPAT; UPAD	OR	ON	2010/05/18 10:44
L4	0	((metal adj air or zinc adj air) near (cell or battery) and cathode near3 (two or second) and negative with (cover or lid or cas\$3)).clm.	US-PGPUB; USPAT; UPAD	OR	ON	2010/05/18 10:44
L5	8	((metal adj air or zinc adj air) near (cell or battery) and cathode near3 (two or second) and anode with (cover or lid or cas\$3)).clm.	US-PGPUB; USPAT; UPAD	OR	ON	2010/05/18 10:44

5/18/10 11:16:54 AM

C:\ Documents and Settings\ jcrepeau\ My Documents\ EAST\ workspaces\ 526967.wsp